Application No. 10/613,556 Response to Office Action

Customer No. 01933

Listing of Claims:

5

Claims 1-8 (Canceled).

- 9. (Currently Amended) A service vehicle comprising:
- a vehicle main body;
- an upper swing body mounted on the vehicle main body and adapted to turn within a width of the vehicle main body;
- a work implement provided on a front side of the upper swing body;
- a seat-side block provided adjacent to a seat on the upper swing body and including a hydraulic tank which contains hydraulic fluid for driving the work implement;
- a step section which defines a path from the seat to outside of the vehicle and which is provided on a front side adjacent to and directly in front of the seat-side block; and
 - a downsizing device for reducing a size of the seat-side block;
- wherein the downsizing device comprises a bubble remover provided in the hydraulic tank for removing bubbles in the hydraulic fluid.

Claims 10-21 (Canceled).

Application No. 10/613,556 Response to Office Action

5

Customer No. 01933

- 22. (Currently Amended) The service vehicle according to claim 9, wherein the path defined by the step section extends from the seat through a section adjacent to and directly in front of the seat-side block to a lateral exit position on the upper swing body.
- 23. (Previously Presented) The service vehicle according to claim 9, wherein the upper swing body comprises a floor on which the seat and the seat-side block are mounted, and the step section is formed as a part of the floor to be flush with the floor.